

## **Subsidence Documents**

All groundwater basins experience subsidence to some degree in response to groundwater pumping. The southwestern Chino Basin in the vicinity of the City of Chino experienced differential subsidence in the late 1980s and 1990s that caused ground fissures. With the implementation of the OBMP in 2000, Watermaster conducted extensive investigations on the cause of subsidence in this area and developed a successful subsidence management program that has completely abated subsidence in the southwestern Chino Basin. The two Subsidence Documents folders contain the seminal reports on the technical evaluation and management of subsidence; and they include the court documents that demonstrate the professional and business like manner in which subsidence is managed.